

## Sure Klean<sup>®</sup> Strippable Masking Cleaning Specification

*Specifier Note: The information provided below is intended to guide the Architect in developing specifications for products manufactured by PROSOCO, Inc. and should not be viewed as a complete source of information about the product(s). The Architect should always refer to the Product Data Sheet and MSDS for additional recommendations and for safety information*

*Specifier Note: Paragraph below is for PART 1 GENERAL, Quality Assurance.*

### Test Area

Test a minimum 4 ft. by 4 ft. area on each type of masonry. Use the manufacturer's application instructions. Let test area dry thoroughly before inspection. Keep test panels available for comparison throughout the cleaning project.

*Specifier Note: Paragraphs below are for PART 2 PRODUCTS, Manufacturers and Products.*

**Manufacturer:** PROSOCO, Inc., 3741 Greenway Circle, Lawrence, KS 66046. Phone: (800) 255-4255; Fax: (785) 830-9797. E-mail: [CustomerCare@prosoco.com](mailto:CustomerCare@prosoco.com)

### Product Description

Sure Klean<sup>®</sup> Strippable Masking (White) is a white temporary coating material for protecting glass, unpainted metal, and polished stone from masonry cleaners being used nearby. It is an easily applied liquid that dries to form a temporary coating, protecting surfaces from contact with masonry cleaning solutions. After cleaning is complete, Strippable Masking is easily removed.

### Technical Data

FORM: White, thick liquid  
SPECIFIC GRAVITY: 0.95  
FLASH POINT: 1 degree F (-17 degrees C) ASTM D 3278  
WT./GAL.: 7.90 lbs.  
VOC content: < 400 g/L  
FREEZE POINT: <-22 degrees F (< - 30 degrees C)

### Limitations

- May damage most synthetic finishes (such as window gaskets, caulk, sealants, acrylic or polycarbonate sheeting, reflective films, vinyl cladding and plastic).
- May damage tinted glass surfaces where tinting has been applied as an exterior surface treatment.
- Not an effective protection material for use with solvent-based paint stripping products.
- Strippable Masking is not for use on plastic "safety glass." Some plastic safety glass closely resembles real glass. Inspect closely before using Strippable Masking on glass.

*Specifier Note: Paragraphs below are for PART 3 EXECUTION, Installation.*

### Application

Before applying, read "Protect" and "Precautionary Measures" sections in the Manufacturer's Product Data Sheet for Strippable Masking (White). Refer to the Product Data Sheet for additional information about application of Strippable Masking.

1. Thoroughly stir contents before applying. Apply one heavy coat or two light coats until surfaces are uniformly white, with no dark areas.
2. Let treated surfaces dry at least one hour before exposing to acidic washing systems, water pressure or other activity.

3. If masking tape has been used around the edge of the windowpane, strip the coating by removing the masking tape and pulling the coating from the glass. When removing from metal surfaces, start at a corner and peel off. Properly applied coatings will come off in large sections. If the coating is difficult to remove, an industrial grade MEK may assist removal. (Use solvent cautiously to avoid damage to solvent-sensitive subsurfaces.)

Note: When used outdoors or indoors and exposed to sunlight, remove product within 3 weeks of application. Failure to remove Strippable Masking within the times specified may make removal more difficult. Under these conditions, an industrial grade MEK may be required for removal.